

### Site Photographs

Aerial Imagery taken from Google on July 31, 2019

Site Photographs were taken October 20, 2022



Photograph 1 – Aerial Image of the site





Photograph 4 - Typical cracking in concrete cap



Photograph 5 - Cracking and sinkhole at corner STA 0+96





Photograph 6 – Areas of missing stone and outfall location circled in red



Photograph 7 – Sinkhole at STA 1+02 and shown rotation of concrete pad for bench.







Photograph 10 - STA 1+40 Outfall



Photograph 11 - Deterioated concrete cap





Photograph 18 – Seawall voids at STA 2+27



Photograph 19 – Poor condition of the concrete cap and dislodged stones STA 2+73-2+95







Photograph 24 - Typical damage of the cross bracing



Photograph 23 - Remaining timber wharf T-head

