

BORROUGH PARK

Summary of Remediation Analytical Data
Fairfield, Connecticut
Last Updated:01/27/2020

Sample ID	US EPA	Bur-C-100	Bur-C-101	Bur-C-102	Bur-C-103	Bur-C-104	Bur-C-105	Bur-C-106	Bur-C-107	Bur-C-108	Bur-C-109	Bur-Dup-A	Bur-C-110	Bur-C-111	Bur-C-112
Sample Depth		0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft
Sample Date		11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019
Lab Sample ID		2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768	2656768
Asbestos PLM 198.1 ²															
% Amosite	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Chrysotile	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Other	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Total Asbestos	1%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%

NA- Not Applicable
Boxed values indicate exceedances of RES DEC
Grey shaded values indicate exceedances of GB PMC
2- Asbestos analysis of Bulk Materials via
40 CFR Part 763, Sub. E, App. E/NYS-DOH
198.1 (PLM) by Eastern Analytical
Services, Inc

BORROUGH PARK

Summary of Remediation Analytical Data
Fairfield, Connecticut
Last Updated:01/27/2020

Sample ID	US EPA	Bur-C-113	Bur-C-114	Bur-C-115	Bur-C-116	Bur-C-117	Bur-C-118	Bur-C-119	Bur-C-120	Bur-C-121	Bur-C-122	Bur-C-123	Bur-C-124	Bur-C-125	Bur-C-126
Sample Depth		0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0.5 ft	0.5 ft	0.5 ft	0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft
Sample Date		11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/14/2019	11/19/19	11/19/19	11/19/19	11/19/19	11/19/19	11/19/19	11/19/19	11/19/19	11/19/19
Lab Sample ID		2656768	2656768	2656768	2656768	2656768	2657535	2657535	2657535	2657535	2657535	2657535	2657535	2657535	2657535
Asbestos PLM 198.1 ²															
% Amosite	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Chrysotile	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Other	NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
% Total Asbestos	1%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%

NA- Not Applicable
Boxed values indicate exceedances of RES C
Grey shaded values indicate exceedances of
2- Asbestos analysis of Bulk Materials via
40 CFR Part 763, Sub. E, App. E/NYS-DOH
198.1 (PLM) by Eastern Analytical
Services, Inc

BORROUGH PARK

Summary of Remediation Analytical Data
Fairfield, Connecticut
Last Updated:01/27/2020

Sample ID	US EPA	Bur-Dup-B	Bur-C-127	Bur-C-128	Bur-C-129
Sample Depth		0-0.5 ft	0-0.5 ft	0-0.5 ft	0-0.5 ft
Sample Date		11/19/19	11/19/19	11/19/19	11/19/19
Lab Sample ID		2657535	2657535	2657535	2657535
Asbestos PLM 198.1 ²					
% Amosite	NA	0.00%	0.00%	0.00%	0.00%
% Chrysotile	NA	0.00%	0.00%	0.00%	0.00%
% Other	NA	0.00%	0.00%	0.00%	0.00%
% Total Asbestos	1%	0.00%	0.00%	0.00%	0.00%

NA- Not Applicable
Boxed values indicate exceedances of RES I
Grey shaded values indicate exceedances of
2- Asbestos analysis of Bulk Materials via
40 CFR Part 763, Sub. E, App. E/NYS-DOH
198.1 (PLM) by Eastern Analytical
Services, Inc