



BUR S7 (Near BP S5)		
Parameter	Concentration	Exceedance
Asbestos in Material by PLM	15%	US EPA

EXCEEDANCE SUMMARY

LEGEND

- Approximate Sample Location
- Non-Soil Sample
- Excavation Areas
- Approximate Site Parcel
- Approximate Parcel Boundary

LOCUS MAP

NOTES

1. Based on 2016 Statewide Orthophotography, Courtesy of CTECO.

Burroughs Park
940 Burroughs Road
Fairfield, Connecticut

October 2019

Tighe&Bond
Engineers | Environmental Specialists