


SUMMARY OF RECLAMATION YARD INSPECTION

Week No.: 9

Inspection Date: November 23, 2016

Logical Environmental Solutions, LLC (LES) visited the Reclamation Yard operated by Julian Enterprises located at the end of Richard White Way in Fairfield for the ninth weekly inspection on November 23, 2016. Julian is continuing to process, screen, and remove material from the pile along the southern portion of the property. The overall height and width of the main pile appears to be lower and narrower than the previous week. There also seems to be less material along the northeastern and eastern faces of the main pile. The material exposed on these faces consists of coarse gravel/cobbles, and larges pieces of concrete. The southeastern face of the main pile contains piles of debris and organic material. Newly exposed suspect-looking soil and newer piles of soil were not observed on the property.

Photographs on the following page display the observed changes to the property. Additional soil samples will be collected throughout the duration of Julian's occupation of the site until December 15, 2016. Please let me know if you should have any questions.



Cindy Knight, LEP
Logical Environmental Solutions, LLC
Office: 860-870-1780
Mobile: 860-402-7069
Email: ck@logicalenvironmental.com



Photograph of activity along the southern side of the main pile. Julian is continuing to make progress removing material for processing and offsite use.



Eastern side of the main pile containing large amounts of course gravel and cobbles.



Northeastern side of the main pile containing large pieces of concrete.



Southeastern face of the main pile with piles of debris and organic material.