

SUMMARY OF RECLAMATION YARD INSPECTION


Week No.: 8

Inspection Date: November 16, 2016

Logical Environmental Solutions, LLC (LES) visited the Reclamation Yard operated by Julian Enterprises located at the end of Richard White Way in Fairfield for the eighth weekly inspection on November 16, 2016. Julian is slowly continuing to process and remove screened material from the pile along the southern portion of the property. They are also removing soil, concrete, and asphalt from the southern face of the pile for onsite screening. The overall height of the main pile appears to be lower.

The northern, eastern, and southwestern faces of the main pile have a large amount of asphalt chunks along their faces. Newly exposed suspect-looking soil and newer piles of soil were not observed on the property. Newer piles of asphalt, concrete, and road-base type soil mixtures with gravel were observed along the top of the main pile and along the northeastern edges of the property.

Photographs on the following page display the observed changes to the property. Additional soil samples will be collected throughout the duration of Julian's occupation of the site until December 15, 2016. Please let me know if you should have any questions.



Cindy Knight, LEP
Logical Environmental Solutions, LLC
Office: 860-870-1780
Mobile: 860-402-7069
Email: ck@logicalenvironmental.com



Southern face of the main pile with additional material removed.



Asphalt pile along the northern side of the main pile.



Asphalt piles along the northeastern portion of the property.



Piles of asphalt long the southwestern face of the main pile.