

SUMMARY OF RECLAMATION YARD INSPECTION


Week No.: 3

Inspection Date: October 14, 2016

Logical Environmental Solutions, LLC (LES) visited the Reclamation Yard operated by Julian Enterprises located at the end of Richard White Way in Fairfield for the third weekly inspection on October 14, 2016. Julian was continuing the removal of soil from the southern side of the pile and removed a considerable amount of material. They also removed the majority of the previously existing small piles of material from the top of the soil mound. A large new pile of soil was observed in the northeast portion of the sound mound area. The soil within this pile was visually inspected and field screened with a photoionization detector (PID). No volatile organic compounds (VOCs) were detected by the PID and no stains or odors were noted so a sample was not collected. No new exposed soil locations indicative of potentially impacted soil were noted.

A figure is attached depicting the observations made by today's inspection and photographs are also included.

Please let me know if you should have any questions.



Cindy Knight, LEP
Logical Environmental Solutions, LLC
Office: 860-870-1780
Mobile: 860-402-7069
Email: ck@logicalenvironmental.com



Main pile area taken from atop the pile looking down and facing south.





New soil pile in northeast portion of the site – top picture facing north, bottom picture facing south.



October 14, 2016 Inspection Notes:

- Red dashed line is approximate extent of material removed from pile.
- Brown filled area is approximate location of new soil stockpiled onsite.



| | |
|---|---|
| Town of Fairfield Dept. of Public Works | |
|  | Construction Material Processing Facility Richard White Way Fairfield, CT |
| DRAWN BY: juls DATE: March 20, 2013 SCALE: 1"=100' | CHK'D BY: M.A. FILE NO: 3340 MAP NO: |

G:\ENGINEERING\Land Projects\B213340\dwg\Construction Plans.dwg, 4/1/2013 1:41:57 PM, Adobe PDF (Temporary)\6334.pr3, 1:100